JAN 1 1 2005

PTO/SB/21 (09-04)
Approved for use through 07/31/2006 OMB 0651-0031
demark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 199

TRADENA **ANSMITTAL FORM**

(to be used for all correspondence after initial filing)

Examine Name
Attorney Docket Nu

5, no persons are required to respond t	o a collection of information unless it displays a valid OMB control number			
Application Number	09/884,048			
Filing Date	June 20, 2001			
First Named Inventor	CUNCHON, FRANCOIS			
Art Unit	2187			
Examiner Name	NGUYEN			

Total Number of Pages in This Submission		Attorney Docket Number		•	T2147-907310			
ENCLOSURES (check all that apply)								
☐ Fee Transmittal Form ☐ Fee Attached ☒ Amendment / Reply ☐ After Final ☐ Affidavits/declaration(s) ☐ Extension of Time Request ☐ Express Abandonment Request ☐ Information Disclosure Statement ☐ Certified Copy of Priority Document(s) ☐ Reply to Missing Parts/ Incomplete Application ☐ Reply to Missing Parts under 37 CFR 1.52 or 1.53		Ass (for Dra Dec Att Lic Pet Pro Rev Cor Ter	signment Papers r an Application) awing(s) claration and Power of orney ensing-related Papers ition ition to Convert to a ovisional Application wer of Attorney, vocation Change of rrespondence Address minal Disclaimer quest for Refund , Number of CD(s) The Commissione required or credit any	or is I	After Allowance Communication to TC Appeal Communication to Board of Appeals and Interferences Appeal Communication to TC (Appeal Notice, Brief, Reply Brief) Proprietary Information Status Letter Application Data Sheet Issue Fee Other Enclosure(s) (please identify below):			
(T2147-907310) for the above identified docket number. SIGNATURE OF APPLICANT, ATTORNEY, OR AGENT								
Firm Name	No. 000181							
Signature								
Printed Name Printed Name Printed Name								
Date January 11, 2005								
CERTIFICATE OF MAILING OR TRANSMISSION								
I hereby certify that this correspondence is being deposited with the United States Postal Service with sufficient postage for first class mail in an envelope addressed to: Mail Stop, Commissioner for Patents, P.O. Box 1450, Alexandria, Virginia 22313-1450, or being facsimile transmitted to the USPTO at, on Signature:								
Name:								

This collection of information is required by 37 CFR 1.5. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.11 and 1.14. This collection is estimated to 2 hours to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

Confirmation No.: 2706



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application for:

First Named Inventor: CUNCHON, FRANCOIS Art Unit: 2187

Appln. No.: 09/884,048 Examiner: NGUYEN

For: COMPUTING MACHINE WITH HARD STOP-TOLERANT DISK FILE MANAGEMENT

SYSTEM

IANAGEMENI

REQUEST FOR RECONSIDERATION

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

Reconsideration in view of the following remarks is respectfully requested. Claims 9-20 are pending with Claims 9-20 having been rejected under 35 U.S.C. 102(e) as anticipated by U.S. Patent No.: 6,393,559 to Alexander.

Independent Claim 9 states that the start up function calls the automatic repair function and the automatic repair function calls the mounting function. Independent Claim 16 includes the feature of mounting an operating system from RAM that includes an automatic repair function, the mounting of the operating system based on a call from the automatic repair function.

Column 1, lines 15-25 and lines 40-63 of Alexander are relied upon for the teaching of these features. However, it is abundantly clear from the description in Alexander that Alexander does not operate in the manner claimed. In contradistinction, Alexander specifically states on column 2 that:

...the boot initialization progress of the BIOS is recorded and, if the boot initialization code fails, the failed boot initialization code is corrected by the BIOS. The boot initialization progress provides an indication of the location in the BIOS initialization code of where the boot initialization failed.

Column 1 of Alexander states that if errors occur during the BIOS or OS initialization, the computer may infinitely reboot or hang (lock-up) at the offending code. However, there is absolutely no teaching or suggestion of this rebooting being based on the automatic repair function as claimed. Moreover, and in relation to independent Claim 16, Alexander's operation is in the BIOS, not mounting of an operating system from RAM that includes an automatic repair function as claimed.

The background of Alexander discloses the BIOS initialization code . . . includes a power-on self test (POST) procedure, to insure that all computer circuitry is functioning before running the operating code. The Office appears to be relying on this POST function of Alexander for anticipating the automatic repair function as claimed.

However, it is clear at least from the above passages that there is absolutely no possibility of the POST function of Alexander being able to automatically call the start up function as claimed.

To the contrary, Alexander specifically states in the Summary that "the boot initialization progress of the BIOS is recorded and, if the boot initialization code fails, the failed boot initialization code is corrected by the BIOS. The boot initialization progress provides an indication of the location in the BIOS initialization code of where the boot initialization failed." Alexander goes on to state that "the self-healing BIOS 30 can identify the initialization code that caused the computer to lock-up and, before that code is initialized again (which would cause the same failure), the self-healing BIOS may skip the failed boot initialization code." Applicant respectfully submits that it is abundantly clear from this passage that an automatic repair function does not automatically call the startup function as claimed.

Claims 9 and 16 are thus allowable. The claims that depend therefrom depart even further from the cited references and are also allowable for the above reasons and the additional feature(s) recited therein.

Applicant respectfully submits the application is in condition for allowance. An early Notice of Allowance is respectfully solicited.

Should the Examiner believe that any further action is necessary to place this application in better form for allowance, the Examiner is invited to contact Applicants' representative at the telephone number listed below.

required by this paper and to credit any overpayment to that Account. If any extension of time is required in connection with the filing of this paper and has not been separately requested, such extension is hereby requested.

Respectfully submitted,

Date: January 11, 2005

Edward J. Kondracki Reg. No. 20,604

Jason H. Vick Reg. No. 45,285

Miles & Stockbridge, P.C. 1751 Pinnacle Drive Suite 500 McLean, Virginia 22102-3833 (703) 903-9000